

## ARTESIA OFFICE COPY

Budget Bureau No. 42-R338.1.  
Approval expires 11-30-49.

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office Las Cruces

063925

Lease No. \_\_\_\_\_

Unit \_\_\_\_\_

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sept. 9, 1948

19

Etz

Well No. 2 is located 660 ft. from N line and 1980 ft. from W line of sec. \_\_\_\_\_SE SW 25  
(¼ Sec. and Sec. No.)16 S  
(Twp.)30 E  
(Range)NMPM  
(Meridian)Square Lake  
(Field)Eddy  
(County or Subdivision)New Mexico  
(State or Territory)The elevation of the derrick floor above sea level is 3798 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The above well was completed 8-20-43 after drilling deeper to 3248'. Estimated gas volume 6,000,000, but U.S.G.S. would not allow gas production from well. It has remained shut in to date. Now request permission to plug and salvage the casing from the well. 8-5/8" was cemented at 478, and 5 1/2" cemented at 2853. Will kill what gas is left and mud to shoe of 5 1/2" casing and place 15 sack cement plug, shoot 5 1/2" about 2400 and attempt to pull. Place 10 sack cement plug at base of salt, and top of salt with mud between. Salvage as much 8-5/8 as possible, place required marker and clean up well location.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. B. MulcockAddress Artesia, New Mexico

By

Title

Owner.