

WELL STATUS REPORT

(To be submitted in quintuplicate on all inactive wells)

C. E. LaRue and B. N. Muncy, Jr.
P. O. Box 196, Artesia, New Mexico 88210

Federal E #2

LEASE NO.
NM 04712

Location 31	Formship 16	Page 30
Footage Location of Well 660 East from South		
1875.97 East from West		
Pool Sg. Lake		
County	State	

RECEIVED

APR 26 1977

O. C. C.
ARTESIA, OFFICE

☒ Oil Well ☐ Gas Well ☐ Temp. Abd. Well ☐

Producing Capability

BOPD 3 MFCGPN
BWPD 30 Date Last Tested 2/1977

Is Well Considered Capable of Production in Paying Quantities?

☒ Yes ☐ No

Capable of Producing in Paying Quantities, Give Reasons For Not Producing Well.

Pumpjack has been brought into yard for repairs.

Is Not Capable of Producing in Paying Quantities, Give Reasons For Not Producing Well at This Time.

RECEIVED

APR 22 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

What Are Future Plans For Operating Well (Include Estimated Dates)?

Well will be back on production as soon as pumpjack repair parts are received.
Present shipping date is supposed to be May 1, 1977.

I hereby certify that the foregoing is true and correct

[Signature]

TITLE Operator

DATE 4/18/77

[Signature]

TITLE ACTING DISTRICT ENGINEER

DATE APR 25 1977