


APPROVE



(SUBMIT IN TRIPLICATE)

Land Office _____
Lease No. **LC-03427**
Unit **RECEIVED**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**ILLEGIBLE**
SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	XI
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. **ELE 144** is located **1900** ft. from **LINE** [S] line and **1900** ft. from [E] line of sec. **34**
10N/4 15E/4 Sec. 34 16E 30E 10W/4
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
SOURCE LAKE **EDDY** **NEW MEXICO**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was a water injection well when Summit took over operations from J. Cline Thompson. Water is being injected through 5 1/2" cas. set at 2932, into open hole from 2932 to 3146. T.D. 3146.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **SUMMIT OIL COMPANY**Address **Rawley Building, Artesia, New Mexico**By **ORIGINAL SIGNED BY
E. J. LEDBETTER**Title **Superintendent**