

RE' VED

C/SF

NEW OIL COM. COMMISSION
 Dec. 1973
 Artesia, NM 88210

NOV 30 '89

Form 9-331
 Dec. 1973

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other W.I.W. S.I.

2. NAME OF OPERATOR

J. Cleo Thompson

3. ADDRESS OF OPERATOR

P.O. Box 237 Loco Hills N.M. 88255

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980 fsl. and 1980 fsl.

AT TOP PROD. INTERVAL: Top perf @ 2918'

AT TOTAL DEPTH: 3746'

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☒

(other) Plug and Abandon

SUBSEQUENT REPORT OF:

☐

☐

☐

☐

☐

☐

☐

☒

5. LEASE - S.A. OFFICE

N.M. 02427

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

West Square Lake Unit

8. FARM OR LEASE NAME

Tract 13

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Square Lake

11. SEC., T., R., M., OR BLK. AND SURVEY OR

AREA J-sec. 34-16sR30e

12. COUNTY OR PARISH

13. STATE

EDDY

N.M.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3740' G.L.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 10-24-89 1. Set C.I.B.P. @ 2820' w/36 sx. cmt. on top. Circulate mud.
 a. Squeeze hole @ 1959' w/ 25 sx. cmt. and tag plug @1932'
 (B.O.S.) 2. Perf @ 1257' spot 25 sx. plug across perfs. and tag plug @1170'
 10-25-89 3. Perf @ 450' spot 50 sx. plug across perf. and tag plug @443'. (T.O.S.)
 10-27-89 4. Pumped 60 sx. cmt. behind surface pipe and dumped 60 5 gal. buckets
 of pea gravel inside 5 1/2 csg. up to 120'. Ran 1 jt. tubing and pumped
 cmt. untill it broke circulation.
 5. Cut csg. off 3' below ground level and set surface marker.

xxxxxxP&A witnessed by Danny Cortez xxxxxxxx

Post ID-2
 12-1-89
 P&A

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Amador P. R. L. TITLE Production Foreman DATE 11-5-89

(This space for Federal or State office use)

APPROVED BY _____ Approved as TITLE _____ of the well bore, DATE 11/28/89
 CONDITIONS OF APPROVAL, IF ANY: Liability until bond is returned until surface restoration is completed,