

Form 9-331a  
(Feb. 1961)

U. S. G. C. COPY


Budget Bureau No. 42-R358.4.  
Form Approved.

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office AM  
Lease No. 02427  
Unit P

copy to 52



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent report of Conversion to wtr. inj. Well

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 20, 1964

Well No. 3 is located 660 ft. from S line and 660 ft. from E line of sec. 34  
SE/4 SE/4 Sec. 34 15-5 30-E N27W  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Square Lake Eddy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

11-13-63 Cleaned out hole.

11-14-63 Started injecting water

RECEIVED  
JAN 27 1964  
U. S. G. C.  
ARTESIA, OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Newmont Oil Company  
Address Rowley Building  
Artesia, New Mexico  
By \_\_\_\_\_  
Title District Superintendent

ORIGINAL SIGNED BY  
H. J. LEDBETTER