

APPROVE

MAR 4 1963
RONNIE E. SHOOK
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office _____
Lease No. **LC 02427**
Unit _____

RECEIVED

MAR 9 1963

ARTESIAN OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	XX
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 26, 1963

Well No. **Leonard No. 5** is located **1900** ft. from **(N)** line and **1900** ft. from **(EX)** line of sec. **34**

SE/4 NW/4 Sec. 34 **16S** **30E** **RUPH**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

SONNE LAKE **LEOY** **NEW MEXICO**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was a water injection well when Mumment took over operations from J. Clee Thompson. Water is being injected through perforations in 4 1/2" liner which is set on bottom, 3006 to 2741. The perforations are from 2834-2873 and 3040-3006. T.S. 3006.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **MUMMENT OIL COMPANY**
Address **ROULEY BLVD.,**
ARTESIA, NEW MEXICO

By _____
Title **Superintendent**