

(SUBMIT IN TRIPLICATE)
**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office Las Alamos
Lease No. 053926
Unit Geo. Exp.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artesia, New Mexico

19

Well No. 9-X is located 3300 ft. from N line and 610 ft. from E line of sec. 32
NNW 1/4 of Sec. 35 16S 30E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Square Lake Kddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3764 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was plugged and abandoned on 11/1/47. Work was done in the following manner. Heavy mud was filled to top of the 570' of surface pipe and a cement plug of 5 sacks was set. From 2865' of oil sting 1705' was recovered leaving a total of 1160' in well. This pipe was filled with heavy mud and a cement plug of 15 sacks was set. Hole filled with heavy mud to top where cement plug of 5 sacks was set. Cement regulation marker was placed and well abandoned.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tammas Petroleum Company

Address 208 Carper Bldg.,

Artesia, New Mexico

By

Title Dist. Mgr.

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 663946
Unit Geo. Litz

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	☒		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October

~~March~~ 30, 1947

Well No. 2-X is located 3300 ft. from N line and 630 ft. from W line of sec. 35

1/4 of Sec 35 164 302 1000
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
SQUARE LAKE KANE NEW MEXICO
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3764 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show plans, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

This well was drilled to a total depth of 3562 feet and plugged back with gravel to 2990 feet. This well has never been productive since drilling and we propose to pull pipe, plug and abandon same by the following method:

Pump a 15 sack cement plug at 2990 feet, pump heavy mud to place where 7" O.D. casing will be parted, this 7" O.D. casing being cemented with 100 sacks cement at 2865 feet, a 15 sack cement plug will be spotted in stub of 7" pipe left in hole. Heavy mud will be pumped in hole to base of 10" O.D. casing which was cemented with 50 sacks cement at 570 feet, another 15 sack cement plug will be spotted just below base of 10" pipe with Heavy mud pumped to surface where a regulation cement plug with marker will be placed. We propose to do this work starting November 1, 1947 work to be done by the Hobbs Pipe & Supply Co.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company H. A. SMOEDEN

Address 208 Carper Building

ARTESIA, N.E. MEXICO

By _____

Title DISTRICT MANAGER & AGENT

(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 163924
Unit Geo. E. 7

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	☒
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 2X is located 3300 ft. from N line and 610 ft. from W line of sec. 35
July 20, 1946

16 S 30 E MMN
(Twp.) (Range) (Meridian)
Sec. 35
(4 Sec. and 64 Sec. No.)
Square 46 Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State nature of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

On June 15, 1946 we ran 2865 ft. of 7" casing and cemented with 100 sacks.
After allowing 72 hours for cement to set, test was made for water shut-off.
Tested okay--drilling was resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BARNETT COCKBURN
Address 304 Garper Building
Artesia, New Mexico

By _____
Title Agent

Form 0-331a
March 1945

(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lead Office Las Cruces
Lease No. 063926
Unit Geo. Etc

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	☒
NOTICE OF INTENTION TO CHANGE PLANE	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 3, 1946

Well No. 9-X is located 3200 ft. from N line and 610 ft. from EX line of sec. 35

NW/4 Section 35 16 South 20 East 10MPN
(N Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Square Lake Elroy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show pump weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We ran 2340 feet of 8 5/8" casing and mudded with 80 sacks mud and 5 aquagel. Work was done May 16, 1946. On May 19, water broke in behind pipe-mud failed to hold. On May 20, we cement 8 5/8" with 15 sacks cement. Let set 72 hours before drilling plug and testing cement.

Drilled plug and tested May 23, 1946

Resumed drilling operations.

Work was done by Halliburton Oil Well Cementing Company

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BARNEY COCKBURN

Address Box 115

Artesia, New Mexico

By _____

Title Agent

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lesse No. 063926
Unit Geo. Etz

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	☒
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artesia, New Mexico April 23, 1946

Well No. 9 - X is located 3300 ft. from N line and 610 ft. from W line of sec. 35

NW/SE/ Section 35 16 South 30 East
(4 Sec. and Sec. No.) (Twp.) (Range)

NMPM
(Meridian)

Square Lake
(Field)

Edy
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

We run 570 feet of 10" pipe in this hole and cemented with 50 sacks of cement. Let set 48 hours before drilling plug and testing cement.

Results: Hold 4ry, tested okay.

Work was done April 21, 1946

Drilled plug and tested cement April 23, 1946.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Barney Cookburn Company

Address Box 115

Artesia, New Mexico

By _____

Title Agent

30-15-04005

Budget Bureau No. 12 1774
Approval expires 11-30-40

Form 9-251a
(March 1942)

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 029431
Unit Geo Ets

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	☒	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 29, 1940

Well No. 2-1 is located 3500 ft. from N line and 610 ft. from E line of sec. 35
NE 1/4 Sec. 35 102 30R N. 30. 30. 30.
(1/4 Sec. and Sec. No.) (Twp) (Range) (Meridian)
Square Lake Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is the intention to drill this well to approximately 3135 feet according to government specifications as follows: Set 8 1/2" at 570 feet and cement with 50 sacks; set 7" OD at 2380 feet and mud with 100 sacks; and set 5 1/2" casing at 2860 feet and cement with 100 sacks.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company JARNEY COCKBURN COMPANY
Address Box 115
Artesia, New Mexico
By _____
Title Agent

