

APPROVED

JUL 25 1962

RONNIE E. SHOOK
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office New Mexico
Lease No. NM-0162
Unit Federal

RECEIVED

JUL 26 1962

D. E. C.
ARTESIA OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Shell Trigg-Federal January 3, 1962, 19

Well No. 4 is located 660 ft. from ~~MY~~_S line and 1980 ft. from ~~EY~~_W line of sec. 5SE/4 SW/4, Sec. 5 16 S 31 E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)North Square Lake Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4053 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1. Pulled rods and pump
2. Spotted 20 sacks regular neat cement plug from 3529' - 3275'.
3. Pulled tubing
4. Spotted 5 sacks cement plug at surface.
5. Erected prescribed marker.

Well plugged and abandoned January 2, 1962

RECEIVED
JAN 5 1962
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address Box 1858

Roswell, New Mexico

By /s/ W. A. Harthorn

Title Division Mechanical Engineer