

TO: N.M.O.C.D.  
Dist. 2  
P.O. Drawer DD  
Artesia, N.M. 88210

MPTM (Rev. 9/82)  
Env. & Reg. Form 100

MOBIL PRODUCING TX. & N.M. INC.  
LEAK MONITORING DATA  
(INDICATING POSSIBLE LEAKS IN FLUID INJECTION WELLS)

LEASE Northeast Square Lake Premier Unit I.D. NO. \_\_\_\_\_ WELL NO. 27

LOCATION (SECTION/BLOCK/SURVEY) Sec 10, T16, R31

FIELD Square Lake San Andres

COUNTY Eddy, N. Mexico N.M. OCD/RRC DIST. 2 (Artesia)

TUBING PRESSURE 500 PSIG

CASING PRESSURE 500 PSIG

*slight* LIQUID OR GAS FLOW PRESENT FROM CASING OR WELLHEAD? YES X NO   

DATE OF OBSERVATION 5-11-83

PERSON REPORTING INCIDENT:

TO HOUSTON OFFICE Raymond Grametbeaur

DATE 5-11-83 TIME 10:20 AM Mountain Time

PERSON NOTIFIED Walter Evans

TO RRC DISTRICT OFFICE Raymond Grametbeaur

DATE 5-11-83 TIME 10:15 AM Mountain Time

PERSON NOTIFIED Betty Rolins

PROPOSED REMEDIAL WORK AND TIME SCHEDULE Pull tbg - repair leak - return to injection within 5 days

REMARKS \_\_\_\_\_

NOTE: COMMISSION MUST BE NOTIFIED 48 HRS. BEFORE TESTING CASING & PACKER.

SIGNED Walter Evans

DATE 5-11-83

COPIES TO: A.J. Alcott  
T.J. Auld  
B.E. Wehrich/CF  
Regulatory

RETURN THIS FORM TO:  
Nine Greenway Plaza, Suite 2700  
Houston, Texas 77046  
Attn: Regulatory Engineering Supervisor

RECEIVED

MAY 13 1983

O. C. D.  
ARTESIA, OFFICE