

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Antonio

Lease No. 042

Unit RECEIVED

JUN 8 1961

SUNDRY NOTICES AND REPORTS ON WELLS O. C. C.
ARTESIA, OFFICE

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

MAY 22, 1961

Well No. 5 is located 2310 ft. from N line and 1700 ft. from E line of sec. 10

Sec. 10, Twp. 10S, R. 11E (Range) 10S (Meridian)
North Square Lake (Grayburg) (Field) Gray (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 4229 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded at 3 PM on May 22, 1961. Drilled 11" hole to 195'. Cemented 195' 8-5/8", 2hr, J-55 new casing with 125 sacks regular neat cement. Circulated an estimated 15 sacks of cement to the surface. After 200 24 hours tested casing with 1000 PSI for 30 minutes. OK

RECEIVED

MAY 31 1961

GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil Company of Texas, a Division of California Oil Company

Address Drewer #5, Rossmore, Texas

By J. L. Lowland

Title District Engineer