



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_

Lease No. LC-029431

Unit \_\_\_\_\_

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 22, 1963, 19\_\_

**Vickera**  
Well No. NO. 5 is located 560 ft. from AN line and 560 ft. from E line of sec. 19  
34/4 34/4 Sec. 19 15 31 42  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Square Lake Eddy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 5-1-63 Fraced Leviington zone down 2" tubing with 15,000 gallons slick water and 15,000 # sand. Well screened out on 1" sand. Ran sandrill tool with 4 ports spaced one foot apart, and sandrilled open hole intervals for 15 minutes as follows: 3182-86, 3174-78, 3167-71, 3142-46. Fraced perforations with 15,000 gallons slick water and 17,000 lbs 20-40 sand. Sandrill tool with 4 ports spaced one foot apart and sandrill open hole 3100-04 for 15 min. Set packers and fraced perforations down 2" tubing with 14,000 gallons slick water and 15,500 # 20-40 sand, 200# P-2. Circulated out frac sand to 3270 and put well back on production. Production 34 bbls oil and 30 bbls water.

RECEIVED

MAY 24 1963

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Newmont Oil CompanyAddress Rowley BuildingArtesia, New MexicoO. C. C.  
ARTESIA, OFFICEORIGINAL SIGNED BY  
By H. J. LEDBETTERTitle Superintendent