

RECEIVED

MAR 29 1966

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION C.
ARTESIA, OFFICE

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-4652	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Ernest A. Hanson		8. Farm or Lease Name Hondo State	
3. Address of Operator P. O. Box 1515, Roswell, New Mexico		9. Well No. 1	
4. Location of Well UNIT LETTER <u>G</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>24</u> TOWNSHIP <u>16-S</u> RANGE <u>31-E</u> NMPM.		10. Field and Pool, or Wildcat Grayburg Jackson	
15. Elevation (Show whether DF, RT, GR, etc.) 4386'		12. County Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The captioned well was plugged and abandoned in the following manner:

- 3/11/66
1. Pulled 930' of 4½" casing. No surface casing was recovered.
 2. A 25 sx. cement plug was set at T.D. 4202'.
 3. A 25 sx. cement plug was set in csg. @ 2286' (Base of Salt).
 4. A 25 sx. cement plug was set in csg. @ 1300' (Top of Salt).
 5. A 100' cement plug was set @ the 4½" csg. stub @ 930'.
 6. A 100' cement plug was set @ 500'.
 7. A 25 sx. cement plug was set @ 350'.
 8. A 5 sx. cement plug was set at the surface and a regulation dry hole marker erected.
 9. The location was then cleaned-up and made ready for NMOCC inspection and approval.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harry F. Schum TITLE Geologist DATE 3/28/66

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE JUN 15 1966

CONDITIONS OF APPROVAL, IF ANY: