


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office LC
Lease No. 056302
Unit 0



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 27, 1963

Well No. Johnson 7 is located 560 ft. from N line and 1980 ft. from E line of sec. 28

SW SE Sec. 28 16 51E NMP
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
East Square Lake Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3-50-63

Sandhill Lovington Zone from 5647-51. started frac. Max. pressure 6500#. Min. Pressure 4500#. Well would not take frac. Recovered sand to TD. Set tension packer at 3402 and put on injection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company NEWMONT OIL COMPANY

Address Rowley Building

Artesia, New Mexico

By _____

Title Superintendent

RECEIVED

OCT 1 1963

ORIGINAL SIGNED BY
H. J. LEDBETTER
ARTESIA, OFFICE