

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
NM OIL CONS. COMMISSION
DRAWER 100
ALBUQUERQUE, NM 88210
Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 063105

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☐

WIW - TA

RECEIVED

2. NAME OF OPERATOR

NEWMONT OIL COMPANY

MAR 22 1983

3. ADDRESS OF OPERATOR

P. O. BOX 1305 ARTESIA, NEW MEXICO 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

2080' FNL & 360' FWL of Sec. 28

7. UNIT AGREEMENT NAME

SQUARE LAKE FLOOD (EAST)

8. FARM OR LEASE NAME

SHELDON

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

SQUARE LAKE (G. SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 28-16S-31E NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3989' GLM

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandon as follows:

6/25/82....Set 50 sack cement plug at 3436'.

6/26/82....Tagged bottom plug at 2580'. Perf base of salt at 1650'. Couldn't pump into perf. Spotted cement plug from 1550' to 1750' across perf. Perf top of salt 735'. Squeezed w/41 sacks cement and shut-in.

6/29/82....Tag cement at 337'. Set dry hole marker at surface.

Location ready for inspection

RECEIVED
JAN 17 1983OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Manager

DATE

1/12/83

(This space for Federal or State Office Use)

APPROVED BY

JAMES A. GILLHAM

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 18 1983

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

Posted 10-12-83
p2a