

Form 9-381a
(Feb. 1951)

APPROVED
MAR 20 1953
RONNIE E. SHOOK
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. 12-360543
Unit _____
RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	AA	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 1, 1953, 19

Well No. 100 is located 1/50 ft. from N line and 1/50 ft. from E line of sec. 22
1/4 Sec. and Sec. No. 16 31C 31N
(Twp.) (Range) (Meridian)
Quartz City New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to clean out to TD 1510, run 140' 4" liner cemented with 35 sacks, perforate liner, acidize, run 1" tubing with packer and connected well up for dual injection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shermont Oil Company
Address Howley Building
Artesia, New Mexico
By _____
Title Superintendent

ORIGINAL SIGNED BY
H. J. LEDBETTER