

(SUBMIT IN TRIPLICATE)

Land Office

Lease No. 22-060971

Unit

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

NOV 13 1962

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	XX
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 30, 1962

Well No. Fidel No. 4 is located 10 ft. from N line and 990 ft. from E line of sec. 2

N 1/4 N 1/4 Sec. 29 16 31E NM 12

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Square Lake Ady New Mexico

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 9-30-62 ran 39' 3 5/8" casing and attached to old 3 5/8" with Bowen casing patch. On 10-4-62 ran 1736' 5 1/2" casing and attached to old casing with Bowen casing patch. On 10-7-62 ran 310' 4" flush joint Hydril liner set at 3563 and cemented with 75 sacks.

RECEIVED
NOV 9 1962
U.S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company NEWMONT OIL COMPANYAddress BOOKER BLDG.ALBUQUERQUE, N.M.ORIGINAL SIGNED BY
By H. J. LEDBETTERTitle Superintendent