

Form 9-281a  
(Feb. 1961)

H. L. O. C. C. COPY

Budget Bureau No. 42-R358.4.  
Form Approved.

(SUBMIT IN TRIPLICATE)

Land Office LC

Lease No. 060723

Unit M

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

RECEIVED

AUG 30 1963

U. S. C. C.  
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 27, 1963

Texas Trading "A"

Well No. 1 is located 660 ft. from S line and 660 ft. from W line of sec. 29

SW SW Sec. 29  
(1/4 Sec. and Sec. No.)

16-S  
(Twp.)

31-E  
(Range)

RMPM  
(Meridian)

Square Lake  
(Field)

Eddy  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-31-63

Ran 314' (10 jts.) of 4" OD 9.5# J-40 hidrill liner with Mamco double float shoe landing collar liner hanger and liner packer. Set liner from 3372-3058 and cemented with 150 sacks Incor cement with 4% gel, 10# salt per sack cement, 12# Gilsomite per sack cement, 1% Haled S. Set liner packer and reversed out 50 sacks cement. Pulled tubing and closed well in.

Perforated with 2 crack jets per ft. from 3208-12 and 3150-58. Acidized with 500 gal. 15% reg. acid. Closed well in. First 24 hours injected 558 hbls. at 2100#.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company NEWMONT OIL COMPANY

Address Rowley Building

Artesia, New Mexico

ORIGINAL SIGNED BY  
H. J. LEDBETTER

By \_\_\_\_\_

Title Superintendent