

GRIER #1

SEE BACK

M-30-16-3)

Report Form No. 1-2541
Approved - 1960 11 11

30-015-09926

(SUBMIT IN TRIPPLICATE)

Lead Office: LAS CRUCES

Case No. 060970

Unit

NSM #73

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANE.....	SUBSEQUENT REPORT OF SHOOTING OR ABANDONING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 18

19 48

Well No. 1 is located 660 ft. from $\frac{1}{2}$ line and 500 ft. from $\frac{1}{2}$ line of sec. 30

Square Lake (City) 160 (County) 313 (M.P.) (Section)

Square Lake (State) Eddy (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(Give names of and reported depths to obstructions, show plans, weights, and length of proposed casing; indicate modifying job, cementing points, and all other important proposed work.)

We mudded hole from 3195' to 3000'. Set 10 sack cement plug from 3000' to 2950'. Knocked 5' off at 1400' and pulled same. Set 15 sack cement plug from 1410' to 1360'. Mudded hole from 1360' to 510'. Set 10 sack cement plug from 510' to 430'. Tried to pull 8' and it would not come. Mudded to surface and cemented marker. then cleaned location for inspection.

RECEIVED

I understand that this plan of work must receive approval by the Geological Survey before operations may be commenced.

Company Boyd-Flemmons drillers

Address 112 South Second, Artesia, New Mexico

By Thomas Boyd

Title Partner

