

Form 9-331a  
(Feb. 1961)

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office

Lease No. **LC 029431**

Unit

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<b>X</b>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 28, 1963

Well No. **Vickers No. 5** is located **1900** ft. from **(N)** line and **1900** ft. from **(E)** line of sec. **30****SW/4 NE/4 Sec. 30**  
(1/4 Sec. and Sec. No.)**16S**  
(Twp.)**31E**  
(Range)**NMPM**  
(Meridian)**SQUARE LAKE**  
(Field)**EDDY**  
(County or Subdivision)**New Mexico**  
(State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was a water injection well when Hummont took over operations from Ambassador on May 1, 1959. Water was injected through 5 1/2" csg. set at 3020, into open hole from 3020-3288. TD is 3288.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **HUMMONT OIL COMPANY**Address **ROWLEY BLDG.****ARTESIA, NEW MEXICO**

By

Title

**Superintendent**