	GAS										
Name of Company Address											
-	DOB 011 P	roperties		ell No.	Unit Letter	Isaation	Box 953	Midland,	Texa. Range	5	
Lease Ti	dewater 3	tate	W	1	I I	32	-	L6 S	Nange	31E	
Date Work Pe	erformed	Pool	South	ne Lake			County	Eddy			
2-26-62 Square Lake Eddy THIS IS A REPORT OF: (Check appropriate block)											
Beginning Drilling Operations Casing Test and Cement Job Other (Explain):											
🔲 Pluggin	Plugging Remedial Work										
5-1/2 inch 15.5# J-55 casing set @ 3520 feet and cemented with 175 sacks. Cement allowed to set 24 hours before testing. 1000# pressure 30 minutes with rig pump. No drop. All water shut off.											
REGEIVED APR 51962 D. D. D.											
Witnessed by Position						ARTESIA, OFFICE Company					
Bill Lloyd Superintendent DOB Oil Properties. Inc. FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY											
		r			AL WELL	DATA					
D F Elev.	DF Elev. TD		PBTD				Producing	Producing Interval		Completion Date	
Tubing Diam	Tubing Diameter Tubin		g Depth	th		ing Diam	eter	ter Oil String		Depth	
Perforated Ir	terval(s)				İ	<u> </u>		 		** ** *** ** ** ** ** ** ** ** ** ** **	
						Producing Formation(s)					
ļ				<u> </u>	S OF WOR		Production	GOR		Gas Well Potential	
Test	t Test BPI		l Production BPD				B P D			MCFPD	
Before Workover											
After Workover											
						I hereby certify that the information given above is true and complete to the best of my knowledge.					
Approved by ML armitter						Name River Mint					
Title OIL ARD GAS INSPECTOR						Position Agent					
Date APR 5 1962						Company DOB 011 Properties. Inc.					