

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

DEC 29 1959

(Submit to appropriate District Office as per Commission Rule 1106) ☐ D. O. O.

Name of Company Newmont Oil Company		Address Boeker Building, Artesia, New Mexico					
Lease State R ✓	Well No. 4	Unit Letter F ✓	Section 32	Township 16S	Range 31E		
Date Work Performed 10-21-59	Pool Square Lake	County Eddy					

THIS IS A REPORT OF: (Check appropriate block)

☐ Beginning Drilling Operations☐ Casing Test and Cement Job☐ Other (Explain):☒ Plugging☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

This old plugged hole was reopened to 1792. After losing two bailers and a string of cable tools in the hole, the well was plugged by spotting 10 sacks of cement at 1470-90, and to 600, 10 sacks of cement from 570-600', and to surface with a marker set in 5 sacks of cement.

Witnessed by D. W. Barry		Position Foreman		Company Newmont Oil Company		
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY						
ORIGINAL WELL DATA						
D F Elev.	T D	P BTD	Producing Interval	Completion Date		
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth			
Perforated Interval(s)						
Open Hole Interval			Producing Formation(s)			
RESULTS OF WORKOVER						
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						
OIL CONSERVATION COMMISSION				I hereby certify that the information given above is true and complete to the best of my knowledge.		
Approved by W. A. Gressett				Name Harmon J. Ludlutter		
Title OIL AND GAS INSPECTOR				Position Superintendent		
Date JUL 17 1961				Company Newmont Oil Company		

OIL CONSERVATION COMMISSION
ARTESIA DISTRICT OFFICE

No. Copies Received 3

DISTRIBUTION

	NO. FURNISHED	
OPERATOR	1	
SANTA FE	1	
PRORATION OFFICE		
STATE LAND OFFICE		
U. S. G. S.		
TRANSPORTER		
FILE	1	✓
BUREAU OF MINES		