



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. LC-663340
Unit 2

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

NOVEMBER 14, 1962

Texas Trading (LTD)
Well No. 4 is located 1950 ft. from N line and 1950 ft. from E line of sec. 33
formerly 4 - Johnson "B"
16 31E 10R
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
QUAKE LAKE Eddy NEW MEXICO
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Change of operator from Ambassador to Newmont Oil Company

Change in name designation, formerly Johnson Lease.

RECEIVED
NOV 15 1962
U. S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company NEWMONT OIL COMPANY
formerly Ambassador Oil Corp.
Address BOGARD BLDG.,
ALBUQUERQUE, NEW MEXICO

ORIGINAL SIGNED BY
H. J. LEDBETTER

By _____

Title superintendent