

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **LC**

Lease No. **056302-B**

Unit **A H**

APPROVED  
SEP 5 1963  
R. L. BUCKMAN  
ACTING DISTRICT ENGINEER

**ILLEGIBLE**  
SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED  
SEP 10 1963

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<b>Change of ownership</b>	<b>XX</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 31, 1963

Well No. **Kennedy 1** is located **1480** ft. from **[N]** line and **660** ft. from **[E]** line of sec. **34**

**NE NE** Sec. **34** **165** **31E** **NMPM**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Square Lake** **Eddy** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **4044** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Change of ownership from BTA to Newmont Oil Company**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **NEWMONT OIL COMPANY**

Address **Rowley Building**

**Artesia, New Mexico**

ORIGINAL SIGNED BY  
H. J. LEDBETTER

By \_\_\_\_\_

Title **Superintendent**