

Form 9-381a
(March 1942)(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las Cruces
Lease No. 056302 B
Unit Johnson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Nov 23, 19 49

Well No. 9 B is located 1980 ft. from [N] line and 1920 ft. from [E] line of sec. 34
SE NE 34 16S 31E N M P M
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
square Lake Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4024 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged the well as follows: loaded the hole to kill the gas, placed a 20 sack cement plug at 5 $\frac{1}{2}$ pipe stub at 1955 feet. Filled the hole with mud to base of 8 5/8 pipe at 788 feet. Then placed a 15 sack cement plug. Filled the hole with mud to 8 5/8 pipe stub at 260 feet. Then placed a 15 sack cement plug and filled the hole with mud to the surface. placed regulation marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company G B SuppesAddress Box 151
Artesia New MexBy B. S. Kennedy
Title Drilling Supt.