


(SUBMIT IN TRIPLICATE)

Land Office ARTESIA

Lease No. 00777 (2)

Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Plugging	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 15, 1958

Levers
Well No. 3 is located 220 ft. from S line and 1980 ft. from W line of sec. 23
16 1/4 24 1/4 Section 33 16 29 ARTESIA
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Forest ddy NEW MEXICO
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well plugged on account of encountering water just under casing at 285'. Plugged back from I.O. of 295' with 8 sack cement plug. Mudded hole back. Cut off casing at 110'. Set 5 sack cement plug on top of 8 5/8" casing. Mudded hole to surface and set cement plug. Did not set marker for marker would have been in way of new location which is 10' west of this hole.

DEC 22 1958
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Highland Corporation, Artesia, New Mexico.

Address _____

By W. J. Pennington
Agent

Title _____