



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 062613-4
Unit Water

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 29, 1956

Well No. 11 is located 1920 ft. from N line and 675 ft. from E line of sec. 23
SE 1/4 Sec. 23 (1/4 Sec. and Sec. No.) 16 27 RMPN
 (Field) (Twp.) (Range) (Meridian)
Eddy New Mexico
 (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As per our conversation we propose to test to the San Andres or not to exceed 2600'. We will set and run 10 3/4" OD casing at approximately 625' to shut off surface water. If production is encountered we propose to bridge hole, pull 10 3/4" casing and run 8 5/8" OD or 7" OD casing and cement same to surface, drill bridge and run 5 1/2" OD casing and cement with 100 sacks or back to 1500'. If we get good show of oil we propose to sand frac and test.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tom Boyd
Address 102 South Second
Artesia, New Mexico

By Agent
Title Robert S. Gaurford