


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las CrucesLease No. LC-029424Unit RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 2, 1963, 19

Henshaw Deep Unit

Well No. 8 is located 1980 ft. from [S] line and 1980 ft. from [W] line of sec. 23NE 1/4 SW 1/4, Sec. 23
(1/4 Sec. and Sec. No.)16 E
(Twp.)30 E
(Range)N 1/2 M
(Meridian)Henshaw-Holfoamp
(Field)Eddy
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 3630 ft. est.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 9025' of 4 1/2" (9.5, 10.5, 11.6# & J-55) casing and cemented to 9036' with 350 sacks Class C cement. Pumped plug with 2200 psi at 4:31 a.m. (MST), July 30, 1963. After WOC 48 hours, tested with 2500 psi for 30 minutes - no pressure drop.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil CompanyAddress Box 1858Roswell, New MexicoOriginal Signed By
By W. E. Bingsen W. E. BingsenTitle Division Mechanical Engineer