

(SUBMIT IN TRIPLICATE)

## UNITED STATES

## DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Los Stuces LC 058301 b

SUNDRY NOTICES AND REPORTS ON WELLS. C.

11
SUBSEQUENT REPORT OF WATER SHUT-OFF
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
SUBSEQUENT REPORT OF ALTERING CASING
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
SUBSEQUENT REPORT OF ABANDONMENT.
SUPPLEMENTARY WELL HISTORY

	1			Hay 6	ry 6,	
Well No.		is located	is located 1980 ft. from Spline and 660 ft. from	line of sec. 25		
\$ <b>E/</b> 4	<b>HE/4</b>	23	165	(5) 31%	v ) 24 244	r) <sup>r</sup>
	Sec, and Sec.		(Twp.)	(Range)	(Meridian)	•
(Field)		(Co	unty or Subdivision)	(State o	or Territory)	
The eleva	tion of t	the derrick flo	or above se	a level is f	t. <i>4034</i>	

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ren 25' 13 3/8" 34% cag. & comented to surface with 22 sacks conent. Drilled with retary tools to 3729" with 7 7/8" hole at T.D. Ren 3729' 5%" 140 J smis, csg. 6 comented with 150 sacks 10% sait coment. Two stage comented 0 525' with 50 sacks coment having 2% CaCl. Ferferated 3474-78 2 shore /ft.; 3536-38, 3543-47, 3551-53, 3681-69 1/ft. Fraced with 25,000 gal. refined oil, 30% 20-40 sd., 750 gal 15% NE acid, with packers set 0 3450, 3525 & 3570', thru 3" tbg.

Swebed load oil and completed 4/29/63 flowing 51 50FD thru %" choice.

I understand Company	that this plan of work must receive approval in writing become described to the control of the c	by the Geological Survey before operations may be commenced.
Address	Bex 151	
	Artesia, N.H.	By B. Commel
		Title Vice x res.