

Form 9-331a  
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYBudget Bureau No. 42-R358.4.  
Form Approved.Land Office New MexicoLease No. NA-0162Unit 0 (Lot 10)

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 9, 1963

Trigg Federal -  
Well No. 10 is located 4290 ft. from XXXX line and 1650 ft. from E line of sec. 6  
Lot 10, Sec. 6 - 16 S - 31 E - NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Square Lake, North Santa Eddy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4010 ft. est.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 3260' of 2-7/8" (6.5#, N-80) casing and cemented @ 3269' with 410 sacks Class "A" neat. Bumped plug with 2500 psi @ 2:15 p.m. (MST), October 7, 1963. After 30 hours, tested casing with 6000 psi for 30 minutes - no pressure drop.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil CompanyAddress Box 1858Roswell, New MexicoOriginal Signed By  
By W. E. Bingham W. E. BinghamTitle Division Mechanical Engineer