## W MEXICO OIL CONSERVATION DIV! ON P.O. DRAWER DD ARTESIA, NEW MEXICO 88210

		artesia, ne	W MEXICO 8	382T0	
					DATE July 7, 1994
Marbob E	nergy Corp			- A	
P.O. Dra	wer 217		. 11 199	34	
Artesia,	NM 88210	3	JUL 11 199		Re: Plugging Reports
Gentlemen	ı:				
Form C-10	3 Report of Pl	ugging for you	r <u>Humble</u> Lease	State '	"23" #1
of the lo Regulatio	cation and fou	nd it to be cl	leared to $\infty$	omply w	has made an inspection ith Division Rules and ided to indicate that the
(V 1.	All pits hav	e been filled	and leveled	i.	
( S 2.	Rat hole and cellar have been filled and leveled.				
( 1 3.	A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete. It must show the quarter-quarter section or unit designation, section, township and range numbers which have been permanently stenciled or welded on the marker.				
•	The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.				
( \ 5.	The dead men and tie downs have been cut and removed.				
( ) 6.	If a one well burn pit loca	lease or last tions have bee	remaining en leveled a	well or and cle	n lease, the battery and ared of all junk & equipment.
locations	for plugged a	nd abandoned v	wells have b	been in	d will be cancelled until all spected and Form C-103 approved.
When all	of the work ou	tlined above h	nas been dor	ne, ple	ase notify this office by filling
in the bl	ank form below have to make m	and returning	g this lette	er to u	s so that our representative
WI LI HOL	nave to make m	bre than one t	TIP CO CIC	100401	
		PECEIV MAK 20 153	ري	OIL O	AND GAS INSPECTOR
FILL IN B	(C) ELOW AND RETUR	M. CON.	DIV.	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	/
I certify for your	that the above inspection and	e work has bee	en done and 1 4-4-95	the ab	ove mentioned lease is ready
LOOK	inspection and	cleare bon	A. A.	NAME	RHONDA NELSON

PRODUCTION CLERK