

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRORATION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Cima Capitan, Inc.				Address P.O. Drawer 1343, Artesia, N.M.			
Lease <i>Red Lake</i> State	Well No. 10	Unit Letter F	Section 22	Township 17S	Range 28E		
Date Work Performed June 25, 1963	Pool Undesignated WC			County Eddy			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain):
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

421' of 7" 20# casing was set in mud, after one hour test hole was dry

RECEIVED
SEP 27 1963
D. E. G.
ARTESIA OFFICE

Witnessed by Thomas F. Welch	Position V. Pres.	Company Cima Capitan, Inc.
--	-----------------------------	--------------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA					
D F Elev.	TD	PBTD	Producing Interval	Completion Date	
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth		
Perforated Interval(s)					
Open Hole Interval			Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by <i>M. L. Armstrong</i>	Name <i>Louis C. Baker</i>		
Title <i>Oil and Gas Inspector</i>	Position Secretary-Treasurer		
Date SEP 27 1963	Company Cima Capitan, Inc.		