

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Cima Capitan, Inc.				Address P.O. Drawer 1343, Artesia, N.M.			
Lease Red Lake		Well No. 10	Unit Letter F	Section 22	Township 17S	Range 28E	
Date Work Performed June 29, 1963		Pool Undesignated			County Eddy		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):
☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Set 808'-4½" 9# new casing with 175 sacks cement, 2 sacks calcaum chloride. Pulled 421' 7" 20# casing. After 24 hrs. baled water out of hole. Tested 1 hr., hole dry.

RECEIVED

SEP 27 1963

O. O. O.
ARTESIA, OFFICE

Witnessed by Thomas F. Welch	Position V. Pres.	Company Cima Capitan, Inc.
--	-----------------------------	--------------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by M. L. Armstrong	Name
Title SECRETARY-TREASURER	Position Secretary-Treasurer
Date SEP 27 1963	Company Cima Capitan, Inc.