

TX 460
BX 1488
TD 3150

8 5/8 c 470 w/50 SX
4 1/2 c 3150 w/100 SX
Perf c 2920-24 62-67
3080-84 3088-3102

9/79 - Backflowing 51 BWPD from surface csg

83' proposes repair 4 1/2" csg leak @ 1331
by setting BP @ 400 + 592 w/50 SX

LIBP @ 2875 w/35'

Perf @ BX 1625

Perf @ 400 + 592
