NUMBER & COP. S RECEIVED				NEW MEXICO OIL CO			ION (Form C-104) Revised 7/1/57
SANTA FE		7-		_	Fe. New Mo		
U.B.G.S.		/-		REQUEST FOR (O		AS FARLOWAR	LE
TRANSPORTER	011				1111 -	10 - 1	New Well
PRORATION OF		1/			JUL 2	1964	Recompletion
This Form C-i able will	104 is be as:	to be subr signed effe	nitted in G ective 7:00 recomplet	the operator before an initial allo UADRUPLICATE to the same l A.M. on date of completion or r io: The completion date shall b the reported on 15.025 psia at 60	ecompletion, be that date i ° Fahrenheit	provided this form is n the case of an oil wel	filed during calendar I when new oil is deliv-
				<b>F</b>	Ort. Worth (Place)	Iexas	July.2, 1954 (Date)
WE AR	e he	REBY RE	QUESTI	NG AN ALLOWABLE FOR A	WELL KNO	JWN AS:	- 1/ - 614 - 1/
later=f				IC. H. J. Loe Federal (Lease)			
K	(Comp	Sec.	30	, T. 165, R. 31E., N	NMPM.,	Square Lake	Pool
Uuit	Later	•					
	-			Elevation 3835 KBM	<b>9,1.964</b> Total	Depth 3310 <sup>J</sup>	PBTD 3182
P	lease	indicate k	cation:	Top Oil/Gas Pay 3085 <sup>1</sup>	Name o	f Prod. Form. Gravb	urg
D	C	В	A				
				PRODUCING INTERVAL -			
	F	G	H	Perforations 3087 -89	and 313		et Notches) epth uting 3116
E	, r	P G	n	Open Hole	Casing	Shoe	ubing
				OIL WELL TEST -		-	Choke
L	K	J	I	Natural Prod. Test: N.A.bb	ls.oil,	bbls water in 💻	_hrs,min. Size_
	Ι.			Test After Acid or Fracture Tre	atment (after	recovery of volume of	oil equal to volume of
M	O N	- 0	- p	load oil used): <u>26</u> bbls.o	il. <b>2</b>	bbls water in <b>24</b> hr	Choke s, <u>()</u> min. Size <u>Pump</u>
				GAS WELL TEST -			
	/E	- 134		Natural Prod. Test:			_Choke Size
Tubing	,Casi	ng and Geme	nting Reco	Method of Testing (pitot, back	pressure, etc	c.);	
Sur	re	Feet	Sax	Test After Acid or Fracture Tre	eatment:	MCF/Day;	Hours flowed
			3 yards	Choke SizeMethod cf 1	esting:		
13-3	<u>78''</u>	35	ready #	Acid or Fracture Treatment (Giv		and the second	
8-5	:/8"	323	50	sand): Lu 000 gallons si	ICK WELEF		
		3290	600	Casing Tubing	Date first	new June 16, 196	4 (Pnapg into gun
- <u>2-</u> '	/			Gil Transporter Continen	tal 011_C	ompany	
							++
Pemari		See att	ached de	ta sheet on completion h	istory of		
Remai	••••••					***************************************	
						•••••••••••••••••••••••••••••••••••••••	
			Las sha ind	compation given above is true and	l complete to	the best of my knowled	
I Approv	hereby ved	y certify t	JUL 2	<u>1964</u> , 19	WATEK##	(Company or Open	itor)
						(Signature)	
	)	11	l.	ssett 1		DINATOR WATERFLO	OD OPERATIONS
By:		J.U.	ANC		Sen	d Communications rega	raing wen to:
Title		JUL	2 1964		2211	Continental Nat	ional Bank Bidg.
					و مربع است الم محمد الم ال	Worth Tovas	76102

On April 9, 1964, Notice of Intention to Drill was approved for this well. The well was spudded on April 9, 1964, when  $13-3/8^{11}$  0.D. conductor pipe was set and cemented at 35°. Rotary tools drilled out from under this conductor pipe on April 13, 1964, and on April 14, 1964,  $8-5/8^{11}$  0.D. surface casing was set at 323° and cemented with 50 sacks. After pressure testing pipe well was drilled to a total depth of 3310°, and a Schlumberger Sonic-Log-Gamma Ray was run. An oil string of 5 1/2″ 0.D. casing was set at 3290° (KBM) and cemented with 150 sacks on 4-21-64. This cement was placed in two stages — 100 sacks around shoe and 50 sacks at top of salt  $\pm$  400°. The casing was pressure tested and found to be holding.

The well was perforated from  $3086^4-90^4$  (4 holes) and  $3134.5^4-47^4$  (6 holes) on 4-28-64. On 4-29-64, these perforations were acldized w/2000 gallons 7.5% acid which communicated up the hole behind the pipe. On 4-30-64 the 5  $1/2^{14}$  0.D. casing was re-cemented through casing perforations with 350 sacks. After drilling out cement, well was squeezed with 100 sacks to 3000 psi.

The upper Premier was abrasijetted from 3087%+89% and the lower Premier from 3135%+46.5%. Both zones were treated with a total of 25,000# of sand and slick water.

The well was tested until June 10, 1964 at which time it was producing 5 BOPD. On June 10, 1964, tubing and rods were pulled from this well, and a retreivable bridge plug was set at 3107<sup>8</sup> between the two sets of perforations at 3087<sup>8</sup>-89<sup>8</sup> and 3135<sup>8</sup>-46.5<sup>8</sup>.

The upper perforations from  $3087^4 - 23^4$  were pressure tested and found not to be open. Apparently all of first frac job went out lower set of perforations from  $3135^4 - 46.5^4$ . The upper perforations were broken down and treated with slick water and 7300# sand.

Well was potentialed for 26 BOPD and 2 BWPD