

NUMBER OF COPIES RECEIVED		5
DISTRIBUTION		
SANTA FE		
FILE	1-	
U.S.G.S.		
LAND OFFICE		
TRANSPORTER	OIL	
	GAS	
PRODUCTION OFFICE		
OPERATOR		3

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Robert A. Dean				Address 823 Midland Tower, Midland, Texas			
Lease Pan Am 13	Well No. 1	Unit Letter A	Section 13	Township 16 S	Range 31 E		
Date Work Performed 6/28/65	Pool W. Mesa Queen			County Eddy			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):
☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Drilled to T. D. of 3400'
 Set 417' of 8 5/8" surface casing with 225 sx.
 Tested cement and test was successful.
 Set 3398' of new 2 7/8" tubing for production string with 80 sx cement.
 Tested to 1000 lbs.
 Test successful. W. O. C.

RECEIVED

JUL 26 1965

F. D. C.
ARTIFICIAL LIFTING

Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>McArmstrong</i>	Name <i>Robert A. Dean</i>
Title SEP 15 1965	Position <i>Owner</i>
Date	Company

OIL AND GAS INSPECTOR