

NUMBER OF COPIES RECEIVED 6	
DISTRIBUTION	
SANTA FE	
FILE	/
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	
OIL GAS	
PRORATION OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Robert A. Dean				Address 823 Midland Tower, Midland, Texas			
Lease Southern Union 15 State	Well No. 1	Unit Letter J	Section 13	Township 16-S	Range 31-E		
Date Work Performed January 28 & 29, 1967	Pool Undesignated <i>Byrdwell</i>			County Eddy			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☒ Other (Explain):
☐ Plugging ☐ Remedial Work **Plug Back to Queen**

Detailed account of work done, nature and quantity of materials used, and results obtained.

1-28-67 Set cast iron plug @3430'
Perforate 3358-70 - 12 holes - Queen sand zone

1-29-67 Acidized Queen sand w/500 gals. M.C.A.
Flowing and cleaning up Queen zone
Preparing to run 4 point test.

RECEIVED

FEB 1 1967

O. C. C.
ARTEZIA, OFFICE

Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>W. A. Gressett</i>	Name <i>Robert A. Dean</i>
Title OIL AND GAS INSPECTOR	Position Operator
Date MAR 18 1967	Company Robert A. Dean