

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other Instructi
verse side)

CATE
on re

Budget Bureau No. 1004-0135
Expires August 31, 1985

40F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injection	5. LEASE DESIGNATION AND SERIAL NO. L C 057798
2. NAME OF OPERATOR S & J Operating Company ✓	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 2249, Wichita Falls, TX 76307	7. UNIT AGREEMENT NAME South Red Lake Grayburg
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FSL & 990' FEL	8. FARM OR LEASE NAME 50 Red Lake Grayburg
14. PERMIT NO.	9. WELL NO. 41
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3632' RKB	10. FIELD AND POOL, OR WILDCAT Red Lake QN-GB-SA
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 35, T17S, R27E
	12. COUNTY OR PARISH Eddy
	13. STATE N. M.

RECEIVED

MAR 21 '89

C. C. D.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) Temporarily Abandon

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was T. A.'d when we took over operations on 10/1/87. We do not know how long it had been shut-in prior to this date. A consulting engineering firm is currently studying this waterflood unit to determine any changes that may be needed in the flood pattern.

APPROVED FOR 12 MONTH PERIOD
ENDING 02-22-90

RECEIVED
FEB 27 8 53 AM '89
CATE
AREA

18. I hereby certify that the foregoing is true and correct

SIGNED

Sandy Robertson

TITLE Petroleum Engineer

DATE 2/22/89

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

3-20-89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side