

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYN. M. O. C.
SUBMIT IN TRIP DATE*
(Other instruction reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0219603-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal BW

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Eagle Creek S.A.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th Street - Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

330' FSL & 330' FEL of Sec. 22-17S-25E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3511' GL

12. COUNTY OR PARISH

Eddy

13. STATE

N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Spud & set 10 3/4" csq.

☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-19-71 - Spudded 5:30 P.M. 6-19-71.

Ran 150' of 10 3/4" 32# J-55 casing, set at 161' with 50 sxs Neat 4% CaCl. Cement circulated. PD 3:45 A.M. 6-20-71. WOC 5 1/2 hrs, drilled out shoe and reduced hole to 9 7/8", resumed drilling.

6-21-71 - TD 1146'. Ran 28 jts of 7" 23# J-55 (1133') casing w/1-shorty shoe, centralizers at 1062, 815, 683', cemented w/350 sxs of Incor Neat 2% CaCl at 1146'. PD 2:45 P.M. 6-21-71. Cement circulated. WOC 18 hrs, pressure tested casing with 500#. Held OK. Drilled out shoe, reduced hole to 6 1/8" and resumed drilling.

RECEIVED

JUL 1 1971

O. C. C.
ARTESIA, OFFICE

RECEIVED

JUN 30 1971

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Edwin L. Leach

TITLE

Engineer

DATE

6-30-71

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD PURPOSES
JUN 30 1971
Date
ACTING District Engineer

*See Instructions on Reverse Side