

Details of bop test

AMOCO Production Company


Pavo Mesa #1

6/21/74


Contractor: Cactus Drlg. Rig 9

Test by Yellow Jacket Tools and Services, Inc.

=====Transposition of the pressure recorder charts=====



=====Transposition of the pressure recorder charts=====



=====Transposition of the pressure recorder charts=====

