NO. OF COPIES RECEIVED	]		Form C-103	
DISTRIBUTION		RECEIVED	Supersedes Old C-102 and C-103	
SANTA FE /	NEW MEXICO OIL CONS	ERVATION COMMISSION	Effective 1-1-65	
FILE /		11111 4 / 407 4		
U.S.G.S.		JUN 1 4 1974	Sa. Indicate Type of Lease	
LAND OFFICE			State Fee	
OPERATOR /		<b>O. C. C.</b>	5. State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PRO	RY NOTICES AND REPORTS ON POSALS TO DRILL OR TO DEEPEN OR PLUG B.	ACK TO A DIFFERENT RESERVOIR.		
1.	7. Unit Agreement Name			
OIL GAS WELL WELL	OTHER-			
2. Name of Operator	8, Farm or Lease Name			
Yates Petroleum	Jackson "AT"			
3. Address of Operator	9. Well No.			
207 South 4th St	5			
4. Location of Well			10. Field and Pool, or Wildcat	
UNIT LETTERM	Und. Lagle Creek San Andres			
			$\Delta M M M M M M M M M M M M M M M M M M M$	
South the second	TOWNSHIP 175	BANGE 25E NMPM.	λημημημημημημηλ	
the				
	12. County			
	3464 '	GR	Eddy	
<sup>16.</sup> Check	Appropriate Box To Indicate N	ature of Notice, Report or Otl	ner Data	
NOTICE OF I	REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB		
		OTHER Set 10-3/4"	<u>csq. X</u>	
OTHER				
17. Describe Proposed or Completed O	perations (Clearly state all pertinent deta	ails, and give pertinent dates, including	estimated date of starting any proposed	

work) SEE RULE 1103.

5-22-74 - Spudded 14 3/4" hole at 3:00 PM 5-22-74.

TD - 239' - Ran 7 jts of 10-3/4", 32# J-55 casing (277') set at 289' and cemented w/160 sx Class C 4% CaCl. Cement circulated. PD 7:00 PM 5-22-74. WOC 12 hours, drilled plug, reduced hole to 9½" and resumed drilling. TD 1172' - Ran 46 jts of 7" 23# J-55 casing (1159') set at 1171' w/ centralizers at 1072 & 725', baskets at 678' and 1-Guide shoe. Cemented w/250 sx Incor mix (6% gilsonite & .6% flocele) 2% CaCl + 150 sx Class C 2% CaCl. PD 1:30 PM 5-24-74. Cement circulated. WOC 18 hrs. Backed off landing jt, nippled up, tested BOP's and casing to 1000#. OK. Drilled plug and tested shoe to 500#. OK. Reduced hole to 6¼" and resumed drilling.

18. I hereby certify that the information above is true and complexity of the second complexity	ete to the be	st of my knowledge and belief. Engineer	DATE_	6-13-74
APPROVED BY_ W. Q. Gressett	TITLE	OIL AND GAS INSPECTOR	DATE_	JUN 1 4 1974

CONDITIONS OF APPROVAL, IF ANY: