

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIP  
(Other instruction  
verse side)ATTN:  
TO:Form approved,  
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

11 0850912

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different section.  
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Yates Petroleum Corporation ✓		8. FARM OR LEASE NAME High Pope "10" Pad.	
3. ADDRESS OF OPERATOR 207 South 4th Street - Artesia, NM 88210		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 430' TWL & 600' FTL of Sec. 13-17S-23E		10. FIELD AND POOL, OR WILDCAT 1-10-23E	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3069' GR	
		12. COUNTY OR PARISH HARRIS	
		13. STATE TX	

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☒  
☐  
☐

REPAIRING WELL

☐  
☐  
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other) SPUD

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

6-5-74 - Spudded 12 1/4" hole at 7:00 PM 6-5-74.

TD 1285' - Ran 40 jts of 8-5/8" 24#, J-55 casing (1268'), 1-Quide shoe, centralizers at 1187 & 849', set at 1282' w/350 sx Incor mix (6% gilsonite 1/4# flocele and 3% gel) + 250 sx Class C 2% CaCl. Cement circulated. PD 2:30 AM 6-11-74. WOC 28 hours. Installed BOP's, nipples up, tested BOP's and casing to 1000#. OK. Drilled shoe and tested to 500#. OK. Reduced hole to 7-7/8" and resumed drilling.

RECEIVED

JUL 11 1974

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*Edith L. Bickman*

TITLE

Engineer

DATE

7-11-74

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED  
JUL 12 1974  
H. L. BICKMAN  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side