Lighty U DI

Form (Ma		UNI D STATES MENT OF THE INTER	SUBMIT IN TRIPL. E (Other instructions on re RIOR verse side)	Porm approved.	lo. 42-R1424.
	GEOLOGICAL SURVEY			NM OSMADA	
	CHAIRDY MOTICES AND DEDODES ON WELLS			6. IF INDIAN, ALLOTTEE OR	THIRE NAME
	SUNDRY NOTICES AND REPORTS ON WELLS				•.
	(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)				
<u>. </u>			TEIVED	7. UNIT AGREEMENT NAME	
	OIL GAS OTHER	न्न अ तृत्व	F: CETYED	Ī	
2.				8. FARM OR LEASE NAME	
	Yates Petroleum Corporation JUL 1 1975			rederal "bi"	: · ·
	ADDRESS OF OPERATOR			9. WELL NO.	
	207 Couth Ath Stro	ot - Artesia, 11	5 88 24 0	3	
4	207 South 4th Street - Artesia, 12 88210 LOCATION OF WELL (Report location clearly and in accordance with any State equirements.* See also space 17 below.)			10. FIELD AND POOL, OR W.	HDCAT
	See also space 17 below.) At surface			Lacle Creck &.	
	330' FNL & 330' PWL of Sec. 27-178-25E			11. SEC., T., R., M., OR BLK.	AND
	330 - FAT & 330 - FAT OF Sec. 27 - FAS 735			survey or area	
				Unit () - /
	PERMIT NO.	15. ELEVATIONS (Show whether	DE ST CR etc.)	12. COUNTY OR PARISH 13	3. STATE
14.	PERMIT NO.	3546' (2007	15.30
		3340	348	1 224/	
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data				
	NOTICE OF INTEN	TION TO:	SUBSE	QUENT REPORT OF:	
		DULL OR LUBER GLEING	WATER SHUT-OFF	REPAIRING WELL	
		PULL OR ALTER CASING	FRACTURE TREATMENT	ALTERING CASIN	
		MULTIPLE COMPLETE		ABANDON MENT*	
		ABANDON*	SHOOTING OR ACIDIZING (Other) Smild & S		-
	REPAIR WELL	CHANGE PLANS	(Note: Report result	ts of multiple completion on	Well
	(Other)			pletion Report and Log form.)	
17.	DESCRIBE PROPOSED OR COMPLETED OPP proposed work. If well is direction	RATIONS (Clearly state all perting on ally drilled, give subsurface to	ient details, and give pertinent date ocations and measured and true verti	s, including estimated date of cal depths for all markers ar	d zones perti-
	nent to this work.)				$\mathcal{Z} \times \mathcal{Z}(\mathcal{M}) \times \mathcal{C}$
5-31-74 - Spudded 14 3/4" hole at 4:45 PM 5-31-74. TD 108' - Ran 6 jts of 10-3/4", J-55 casing (185') set at 198' K Cemented w/125 sacks Class C 4% CaCl. PD 9:30 PM 5-31-74. Cemented w/125 sacks Class C 4% CaCl.					
					• 1
					t'' i
	circulated. WOC 1	drilled coment	, xe÷		
	duced hole to 9½" and resumed drilling.				
	TD 1121' - Ran 36 jts of 7" 23#, J-55 casing (1109') set at 1221'.				
	Centralizers at 1041', basket at 647' and 1-Guide shoe. Comented w/300				
	saz of Incor mix and 150 saz Neat 2% CaCl. PD 1:00 PM 6-2-74. Cement				
	saz of Incor mix a	ind 150 saz Neat	2% CaC1. PD 1:00	PM 9-4-74.	rement
	circulated. WOC]	18 hours. Backed	d off landing jt a	nd nippled up;	and

tested BOP's and casing to 1000#. OK. Drilled plug and tested shoe to 500#. OK. Reduced hole to 64" and resumed drilling.

RECENT DATE OF THE PROPERTY OF

J		
18. I hereby certify that the foregoing is true and correct SIGNED	TITLE Engineer	DATE 6-27-74
(This space for Federat or State office use)	TITLE	DATE
O PAITIONS OF APPROVAL, IF ANY:		