

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

FEB 13 1992

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

NM 0439900

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Federal CB #2

9. API Well No.

30-015-21365

10. Field and Pool, or Exploratory Area

Eagle Creek SA

11. County or Parish, State

Eddy, NM

**SUBMIT IN TRIPLICATE**

1. Type of Well

☐ Oil Well ☐ Gas Well ☐ Other P&A

2. Name of Operator

YATES PETROLEUM CORPORATION (505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit ~~1~~, ~~330'~~ FSL, 2310' FWL, Sec. 15-T17S-R25E

K 1650' (528)

**12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

**TYPE OF SUBMISSION**

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

**TYPE OF ACTION**

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plugged and abandoned well as follows: Notified Shannon Shaw, BLM, Carlsbad, NM of plans to P&A well. (No rods in well.) RIH w/46 jts 2-3/8" tubing. Bottom at 1303'. Pumped 2 bbls brine followed w/4 sx cotton seed hulls in 8 bbls brine down tubing on vacuum. LD 8 jts tubing. Put bottom tubing at 1157'. Mixed 25 sx Class "C" cement w/2% CaCl and displaced down tubing with 2.5 bbls brine. Broke circulation while pumping cement. Calculate plug from 1157-707'. POH with tubing. WOC 3 1/2 hrs. RIH w/20 joints tubing and tag TOC at 618'. Actual bottom plug from 1157-618'. Circulated 5 1/2" with 12 bbls MLF. LD 10 joints tubing and put bottom at 310'. Mixed 35 sx Class "C" cement and pumped down tubing. Circulated good cement to surface. Top plug from 310'-surface. LD 10 joints tubing. Flushed lines and BOP with water. Removed BOP. Cathy Queen, BLM, Carlsbad, NM, witnessed tagging bottom plug and spotting top plug.

Plugging completed 1-30-92.

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

Post ID-2  
2-14-92  
P&A

14. I hereby certify that the foregoing is true and correct

Signed Shannon Shaw Title Production Supervisor

Date 2-4-92

(This space for Federal or State office use)

Approved by \_\_\_\_\_ Title \_\_\_\_\_  
Conditions of approval, if any:

Date 2/10/92