

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND	FILE
OPER	OR

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-101
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Well State <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Other <input type="checkbox"/>
1. Name of Operator Yates Petroleum Corporation		6. State Oil & Gas Lease No. B-2175
3. Address of Operator 207 So. 4th, Artesia, NM 88210		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>16S</u> RANGE <u>30E</u> NMPM.		8. Form or Lease Name Marco Polo "EA" St.
15. Elevation (Show whether DF, RT, GR, etc.)		9. Well No. 1
		10. Field, Pool, or Wildcat <u>West Henshaw-Wolfcamp</u> <u>Wildcat-Wolfcamp</u>
		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASINGS <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated cost of proposed work) SEE RULE 1103.

On September 30, 1975 well was sand-frac'd thru original perforations 8630-35 and 8684-92 using 4000 g. 20% DS-30 acid and 1200 g. Dolotrol acid w/20 tons CO and 300# Westblock 111-X. Treatment went on vacuum overnight. Well was swabbed October 1-3 recovering acid water and some oi. The gearbox has been broken and after considerable searching and imploring we finally got the pumping unit patched up and back to working. As of November 19 well has been producing 40 BOPD.

RECEIVED
NOV 25 1975
ARTICLE 10, N.M.S.A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Eddie M. Gessett</u>	TITLE <u>Engineer</u>	DATE <u>11/24/75</u>
APPROVED BY <u>W. R. Gessett</u>	TITLE <u>SUPERVISOR, DISTRICT II</u>	DATE <u>NOV 26 1975</u>

CONDITIONS OF APPROVAL, IF ANY: