Submit 3 Copies to Appropriate District Office

State of New Mexico argy, Minerals and Natural Resources Department

Form C-10	3 0
Revised 1-1	49

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM \$8210

CONDITIONS OF AIFROVAL, IF ANY:

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504 2088 VED

WELL API NO. 30-015-21535

ADD - & 1001

5. Indicate Type of Lease FEE

_ DATE 4/10/91

DISTRICT III			APR - 0 1331			<u></u>	
1000 Rio Brazos Rd., Aztec, NM 874	10		o. c. p.	6. State Oil & Gas	Lease No.		
SUNDRY N	OTICES AND REPORTS O	N WE					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name					
1. Type of Well: OL GAS WELL XX WELL	OTHER			EMPIRE ABO	UNIT "E"		
2. Name of Operator ARCO OIL & 'GAS CO	OMPANY			8. Well No. 37	1		
3. Address of Operator	JEH ANT		9. Pool same or Wildcat				
	HOBBS, NEW MEXICO 8	8240		EMPIRE - A	BO		
4. Well Location Unit LetterD:	1195 Feet From The NORT	Н	Line and 10	Foot From T	WEST	Line	
Section 35	Township 17S		mage 28E	OMPM ED-	04	County	
	//////////////////////////////////////		DF, RKB, RT, GR, etc.) 1' GR				
11. Chea	ck Appropriate Box to Ind			port, or Other I	<i>'111111111111111111111111111111111111</i>		
	INTENTION TO:			SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	□ A	LTERING CASING		
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING	OPNS. P	LUG AND ABANDO	DNMENT [
PULL OR ALTER CASING]		CASING TEST AND CEMENT JOB				
OTHER:			OTHER: TEMPORAR	LY ABANDON	· -	<u>x</u>	
12. Describe Proposed or Completed Owork) SEE RULE 1103.	perations (Clearly state all pertinent d	letails, an	d give pertinent dates, includi	ng estimated date of st	arting any proposed		
TA & HOLD WELL BORE	FOR FIELD BLOW DOWN						
T.D. 6390 P.B.D. 6	185 PERFS: 6156-61	66					
3/2/91 MIRU WEL PULLED 1 OUT WITH	L HAD BEEN KILLED DA 95 JTS, RAN BACK IN TBG.	Y BEF WITH	FORE, UNFLANGED I SCRAPPER & BIT T	3-1, NIPPLE CO CLEAN CSG	D UP BOP, , THEN CAME		
BRINE WA	RAN TBG BACK IN HOLE WITH CIBP, SET BP AT 6135, CIRCULATED CSG WITH 8.6 BRINE WATER & WT675, DOWN TBG OUT CSG, TESTED TO 500#, CHART ATTACHED NMOC M. STUBBLEFIELD OK'ed TEST. PULLED TBG, LAYED DOWN, REMOVED BOP INSTALLED B-1 FLANGE W/1 JT TBG IN HOLE. RIGGED DOWN. SET CIBP 6135						
- PRESSURE	_TEST CHART ATTACHED				·		
I hereby certify that the information above is	true and complete to the best of my knowl	edge and l	belief.				
SIGNATURE Samuely		TITL	Adminstrative S	Supervisor	DATE April	2, 1991	
TYPE OF PRINT NAME Jemes D	. Cogburn				TELEPHONE NO. 3	92-1600	
(This space for State Lies)							