

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NMOCC COPY

PERMIT IN TRIPL
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

DEC 26 1978

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	2. NAME OF OPERATOR Yates Petroleum Corporation	3. ADDRESS OF OPERATOR 207 South Fourth Street - Artesia, NM 88210	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL & 1980' FWL of Section 21-17S-25#	5. LEASE DESIGNATION AND SERIAL NO. NM 0219603	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	7. UNIT AGREEMENT NAME	8. FARM OR LEASE NAME Federal "BZ" Com	9. WELL NO. 12	10. FIELD AND POOL, OR WILDCAT Eagle Creek Permo Penn	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21-17S-25E Unit K NMPM	12. COUNTY OR PARISH Eddy	13. STATE NM
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3572' GR											

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input checked="" type="checkbox"/> Recompletion	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

A blanking plug was set in Strawn packer at 7568'. Pulled tubing and perforated casing and treated as follows:

Strawn 7414-7420', 12 0.34", treated w/1000 gallons 15% DS-30; swabbed dry, gas TSTM.

Canyon 6817-20'; 6822-27'; 6833-36', 14 0.34", treated w/1000 gallons 15% DS-30

Cisco 6680-6692', 13 0.34", treated w/1000 gallons 15% DS-30

Wolfcamp 6392-6396', 8 0.34", treated w/1000 gallons 15% DS-30

Set retrievable bridge plug at 6897' (PBTD 6896') and set 2-3/8" tubing on Guiberson Uni VI packer at 6367'. Swabbed perfs 6392-6836'. Well flowed after clean up, 100# on 1/4" choke = 160 MCFFD. Shut well in. Waiting on sales contract.

RECEIVED

DEC 19 1978

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Eddie M. Valdez TITLE EngineerDATE 12-19-78

(This space for Federal or State office use)

APPROVED BY J. S. Lara TITLE ACTING DISTRICT ENGINEERDATE DEC 20 1978

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side