

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPER OR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes C-101
C-102 and C-103
Effective 1-1-65

RECEIVED

SUNDY NOTICES AND REPORTS ON WELLS DEC 16 1975
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well Oil <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	2. Name of Operator Yates Petroleum Corporation	3. Address of Operator 207 South 4th Street - Artesia, NM 88210	4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1400</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>17S</u> RANGE <u>26E</u> NMPM.	5. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	6. Survey or Lease Name Artesia, Office	7. Unit Agreement Name	8. Form or Lease Name Caskey "EV" Com	9. Well No. 1	10. Field or Pool, or Willcat Undesignated	11. Elevation (Show whether DF, RT, GR, etc.) 3428' GR	12. County Eddy
--	--	--	---	---	--	------------------------	--	------------------	---	---	--------------------

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASINGS <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPHS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated cost of work) SEE RULE 1103.

Spudded 17½" hole at 12:30 PM 11-19-75.

TD 370' - Ran 8 joints of 13-3/8" 48# K-55 (363') set at 360'. Cemented w/250 sacks of Class "C" 4% CaCl. PD 8:30 PM 11-19-75. Cement circulated. WOC 12 hours, cut off landing joint and nipped up flow nipple. Drilled cement, reduced hole to 12¼" and resumed drilling.

TD 1286' - Ran 29 joints of 8-5/8" 24# casing (1286') set at 1282' w/ 450 sacks Howco-lite w/5% gil 0.5% flocele 2% CaCl + 150 sacks of Class "C" 2% CaCl. 1-Tex Pattern shoe, 2 centralizers, 2 baskets 782 & 694'. PD 11-21-75. Cement circulated. WOC 18 hours. Nipped up, installed BOP's tested to 1200#. OK. Drilled cement and tested shoe to 600#. OK. Reduced hole to 7-7/8" and resumed drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine Johnson TITLE Geol. Secty DATE 12-14-75
APPROVED BY W.A. Gressett TITLE SUPERVISOR, DISTRICT II DATE DEC 16 1975
CONDITIONS OF APPROVAL, IF ANY: