

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	✓
U.S.G.S.	
LAND OFFICE	
OPER OR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-104  
Effective 1-1-66

RECEIVED

SUNDY NOTICES AND REPORTS ON WELLS JAN 23 1976

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DEEPER IN AN AREA.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. <b>O. C. C.</b> <b>ARTESIA, OFFICE</b>	3. Unit Agreement
4. Name of Operator <b>Yates Petroleum Corporation</b>	5. <b>Morley "EW" Com</b>	6. Well No. <b>1</b>
7. Address of Operator <b>207 South 4th Street - Artesia, NM 88210</b>	8. <b>Und. Morrow</b>	9. Field
10. Location of Well UNIT LETTER <b>P</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>27</b> TOWNSHIP <b>17S</b> RANGE <b>25E</b> NMPM.	11. <b>Eddy</b>	12. County
13. Elevation (Show whether DE, RT, GR, etc.) <b>3515' GR</b>	14. <b>Eddy</b>	15. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	OTHER <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including completion date, if applicable.) SEE RULE 1103.

Spudded a 17½" hole at 3 AM 1-14-76.

TD - 325' - Ran 8 joints of 13-3/8" 48# H-40 ST&C R3 new casing (322.47') set at 320' KB. Cemented by Denton w/200 sacks of Class "C" 4% CaCl. Cement circulated. PD 6:00 PM 1-14-76. WOC 12 hours nipples up, drilled plug, reduced hole to 12½" and resumed drilling.

TD 1220' - Ran 29 joints of 8-5/8" 24# K-55 ST&C new casing (1222.14') set at 1220'. 1-Tex Pattern shoe, centralizers at 1180 and 620', basket at 580'. Cemented by Denton w/350 sacks of Class "C" 2% CaCl. Cement circulated. PD 12:30 AM 1-17-76. WOC 18 hours, cut off landing joint, nipples up and installed BOP's, tested to 1000#. OK. Drilled plug and tested shoe to 600#. OK. Reduced hole to 7-7/8" and resumed drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine Tomlinson TITLE Geol. Secty DATE 1-22-76

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JAN 23 1976

CONDITIONS OF APPROVAL, IF ANY: