	·			•			••	• .
NO. OF COPIES RECEIVED	3			. · ·	*	Form C-103		· -
DISTRIBUTION				· • •		Supersedes C-102 and 0		
SANTA F	1		NEW MEXICO OIL CONSI	ERVATION COM	MISSION	Effective 1	-1-65	
FILE		1					· · • • · · · · · · · · · · · · · · · ·	
U,5.G.S.				RECE	IVED >	59. Indicate Ty		FeuXX
LAND FICE	_		-			Stute		
OPE OR				MAR 5	1976	5, State Off & C		Proc.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN ON PLUG BACK TO A DIFTERENT DERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101, FOR SUCH PROPOSALS) DEFIDE								
GAS	. 🕅	k	OTHER.	ARILSIA,	UPFICE	7. Unit Agreem		
· · · · me of Operator							we Nante	0.000
Yates Petroleum Corporation V							"FL"	Com
3. Address of Operator								
207 South 4th Street - Artesia, NM 88210								
4. Location of Well								ildaat Und
UNIT LETTER F. 1980 FEET FROM THE North LINE AND 1940 FEET FROM							Farms	Morrow
THEWest								
15. Elevation (Show whether DF, RT, GR, etc.)						12. County		
		IIII	3345	GR		Eddy		MITT
16.	Ch	eck Apr	propriate Box To Indicate N	lature of Notic	e, Report or Oth	ier Data		
лот			ENTION TO:		SUBSEQUENT		F:	
PERFORM REMEDIAL WORK			PLUG AND ABANDON	REMEDIAL WORK			EPF19 C	
TEMPORARILY ABANDON	<u>_</u>		e	COMMENCE DRILL		71.0	s j AlbAl	CONMENT
PULL OR ALTER CASING			CHANGE PLANS		CEMENT OF X			
OTHER				OTHER				· []
				ails and airs part	inset dat a stabilit	ing a she in the state of the s		C: 270025.

...

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includion estimates work) SEE RULE 1903.

Spudded a 17<sup>1</sup>/<sub>2</sub>" hole at 1:30 PM 2-26-76.

Ran 10 joints of 13-3/8" 48# (409') of casing, set at 405'. Cemented w/250 sacks of Halli-Lite Class "C" 4% CaCl. Cement circulated. PD 10:00 PM 2-26-76. WOC 12 hours, NU, cut off landing joint, drilled plug, reduced hole to 124" and resumed drilling.

TD 1374'. Ran 32 joints of 8-5/8" 24# K-55 ST&C (1378.81') of casing set at 1374' KB. 1-Tex Pattern Shoe, centralizers at 1330' and 584', cement baskets at 634 & 538'. Cemented by Denton w/350 sacks of Lite - 2% CaCl, followed w/150 sacks of Class "C" + 2% CaCl. PD 8:15 PM 2-28-76. Cement circulated. WOC and cement dropped,filled hole to surface w/8 yards of Ready-mix down outside 8-5/8" casing. WOC 18 hours, nippled up, installed BOP's and tested to 1000#. OK. Drilled plug and tested casing to 600#. OK. Reduced hole to 7-7/8" and resumed drilling.

18. I hereby certify that the information above is true and complet	e to the beaution conference and the beaution of the beaution of the second s	· · · · · · · · · · · · · · · · · · ·
SIGNED Christines Tomlenson)	Geol. Secty	3-4-76
APPROVED BY W. G. Gressett	TITLESUPERVISOR, DISTRICT II	MAR 5 1976

CONDITIONS OF APPROVAL, IF ANY: