	<b>—</b> ———————————————————————————————————		
NO. OF COPIES PECEIVED -		Form C-103	
DISTRIBUTION	RECEIVED	Supersedes Old C-102 and C-103	
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65	
FILE	MAY 3 1976		
U.S.G.S.	0 15/0	Sa. Indicate Type of Lease	
LAND OFFICE		State X Fee	
OPERATOR	O. C. C.	5. State Oil & Gas Lease No.	
	ARTESIA, OFFICE	647	
(DO NOT USE THIS FORM FOR USE MAPPE	IDRY NOTICES AND REPORTS ON WELLS Hoppinals to tall of to being or flug back to a different reservoir.		
1. OIL X GK5 WELL	0THER-	7, Unit Agreement Name	
2. Nation of Operator		8. Farm of Lease Name	
Atlantic Richfield C	Empire Abo Unit "G"		
3. Aduress of Operator		9. Well No.	
P. O. Box 1710, Hobb	os, New Mexico 88240	321	
4. Location of Well		10. Field and Pool, or Wildort	
UNIT LETTER I	1520 FEET FROM THE South LINE AND 250 FEET FROM	Empire Abo	
	CTION 33 TOWNSHIP 17S RANGE 28E NMPI		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy	
16. Chec	k Appropriate Box To Indicate Nature of Notice, Report or O	ther Data	
		NT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB X SU	irface	
OTHER			
WORK SEE RULE 1103,	Coperations (Clearly state all pertinent details, and give pertinent dates, includir		
	pudded 11" hole @ 12:30 PM 4/23/76. Drld 11" hol		
	w/8-5/8" OD 24# K-55 csg, set csg @ 550'. FC @		
sx Cl C cmt cont'g 4% gel, $\frac{1}{4}$ #/sk celloflake, 6# salt/sk, 2% CaCl followed by 100 sx Cl C cmt			
	% CaCl. Plug down @ 3 AM 4/24/76. WOC 12 hrs &		
<b>csg to 1000</b> # 30 mins	OK. Surface csg cmtd in accordance w/OCC Rule 10	7, Option 2. The following	

- information is reported for this option.
- 1. Volume of cmt slurry for 1st 100 sx was (188 cu ft) and 2nd 100 sx was (132 cu ft), brand name, additives & sequence of placement were as shown above.
- 2. Approximate temperature of cmt slurry when mixed was 72°.
- 3. Estimated minimum formation temperature in zone of interest was  $66^{\circ}$ .
- 4. Estimate of cmt strength @ time of test was 1800 psi.
- 5. Actual time cement in place prior to starting test was 12 hrs.

Resumed drlg 7-7/8"hole @ 4 PM 4/24/76.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	TITLE Dist. Drlg. Supv.	
APPROVED BY U & frisset	ТІТЕ	DATE
CONDITIONS OF APPROVAL, IF ANY:		